

United States Department of the Interior

BUREAU OF LAND MANAGEMENT CEDAR CITY DISTRICT BEAVER RIVER RESOURCE AREA 176 East D.L. Sargent Dr. Cedar City, Utah 84720



IN REPLY REFER TO: UT-044 3809 UTU-67116

June 27, 1997

Mr. D. Wayne Hedberg Division of Oil, Gas, & Mining 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Dear Mr. Hedberg:

This letter is in regards to correspondence, dated May 14, 1997, from Hecla Mining Co. to your Division, requesting plugging of the Escalante Mill tailings pond underdrain. The tailings pond is located entirely on public lands within Secs. 3 & 10, T. 36 S., R. 17 W.

Ed Ginouves of my staff inspected the site on June 26, 1997 to confirm the surface integrity of the tailings cap and measure the flowrate of the underdrain. The tailings pond soil cap has a stable cover of vegetation and no evidence of surface water penetration of the cap was noted. The flowrate of the underdrain was measured at the discharge point at the mill and was found to be 0.5 liters/min. We are satisfied that this extremely low flowrate is an indication that the pore fluids in the tailings pile are essentially drained, and that the tailings pile cap is functioning as designed, and has isolated the tailings from the hydrologic system. It would be acceptable to BLM to plug the underflow drain pipe at this time.

If you have an questions or concerns, please contact Ed Ginouves at (801) 865-3040.

Sincerely,

Craig L. Egerton Area Manager